



Control Hub 1 GoBilda 5203
FTC -



DriverHub 3

Robot Connected

Network: FTC-A3Qn
Ping: 4ms - ch 6

DS: 100%

12.68 V
(12.68 V)

Practice Timer
2:30

2024

Main OpMode

INIT


Expansion Hub 2 was missing at startup. Robot Restart required for hub operation.

The Robot Controller and Driver Station app versions do not match, which is required for competition. You should update the Driver Station app.


Both the Robot Controller and Driver Station support 5 GHz. You should consider selecting a 5 GHz Wi-Fi channel.

Status : Robot is stopped

Configure Robot



□New□□□□□□□□



□Control Hub Portal□□□□□□□□

Save Cancel Scan



Press the 'Save' button to persistently save the current configuration

Press the 'Scan' button to rescan for attached devices

USB Devices in configuration:



Control Hub Portal
(embedded)



Control Hub Control Hub

Done Cancel

Control Hub Portal

(embedded)

Control Hub



Motors

Done

Cancel

Control Hub

Motors

Servos

Digital Devices

Analog Input Devices

I2C Bus 0

GoBilda 5203 GoBILDA 5202/3/4 series motor

Done

Cancel

Port Attached

0

GoBILDA 5202/3/4 series

motor


motor name

1


Nothing

NO DEVICE ATTACHED

Done Save



practice



Activate

New

Available configurations:



practice

Edit

Activate

Delete

test

Edit

Activate

Delete

Configure from Template



Revision #2

Created 2 September 2024 09:58:37 by Yuki Terasaki / 23232

Updated 2 September 2024 10:18:17 by Yuki Terasaki / 23232