


FTC Driver Station



Robot Connected TeleOp



Main OpMode INIT

Robot Connected

Network: FTC-A3Qn  
Ping: 4ms - ch 6

DS: 77%

12.98 V (12.97 V)

Practice Timer: 2:30

2024

Main OpMode

INIT

Expansion Hub 2 was missing at startup. Robot Restart required for hub operation.

The Robot Controller and Driver Station app versions do not match, which is required for competition. You should update the Driver Station app.

Both the Robot Controller and Driver Station support 5 GHz. You should consider selecting a 5 GHz Wi-Fi channel.

Status : Robot is stopped

Status: Initialized

Robot Connected

Network: FTC-A3Qn  
Ping: 4ms - ch 6

DS: 77%

12.97 V (12.97 V)

Practice Timer: 2:30

2024

Main OpMode

Status : Initialized

Expansion Hub 2 was missing at startup. Robot Restart required for hub operation.

The Robot Controller and Driver Station app versions do not match, which is required for competition. You should update the Driver Station app.

Both the Robot Controller and Driver Station support 5 GHz. You should consider selecting a 5 GHz Wi-Fi channel.

Status Started



